

ER REGULATORY CONTACT RECORD

Date/Time April 20, 2004/2 20

Site Contact(s) Annette Primrose
Phone 303 966-4385

Regulatory Contact Harlen Ainscough
Phone 303 692-3337

Agency. CDPHE

Purpose of Contact Best Management Practices at IHSS Group 500-5

Discussion

PCB samples were recently collected at IHSS group 500-5 – the transformer leak at 558-1. These results all came back below action levels. However, some of the surrounding soils appear to be stained with a non-PCB-contaminated oil.

Therefore, the Site will remove the transformer slabs along with the stained soils as a Best Management Practice. The area will be backfilled with clean fill dirt after removal is complete.

Contact Record Prepared By Annette Primrose

Required Distribution

M Aguilar, USEPA
S Bell, DOE-RFFO
J Berardini, K-H
B Birk, DOE-RFFO
L Brooks, K-H ESS
M Broussard, K-H RISS
L Butler, K-H RISS
G Carnival, K-H RISS
N Castaneda, DOE-RFFO
C Deck, K-H Legal
S Gunderson, CDPHE
M Keating, K-H RISS
G Kleeman, USEPA
D Kruchek, CDPHE
D Mayo, K-H RISS

R McCallister, DOE-RFFO
J Mead, K-H ESS
S Nesta, K-H RISS
L Norland, K-H RISS
K North, K-H ESS
E Pottorff, CDPHE
A Primrose, K-H RISS
R Schassburger, DOE-RFFO
S Serreze, K-H RISS
D Shelton, K-H ESS
C Spreng, CDPHE
S Surovchak, DOE-RFFO
K Wiemelt, K-H RISS
C Zahm, K-H Legal

Additional Distribution

Harlen Ainscough CDPHE
Gerry Kelly, KH Team
Nick Demos, KH Team

